
FineMarker: The Technology



Dimensions	1130 mm x 980 mm x 1060 mm (44,5 x 38,6 x 41,7 inches)
Max. working area	720 mm x 430 mm (28,3 x 16,9 inches)
Max. height of workpiece	Approx. 156 mm (Approx. 6,14 inches)
Processing speed	FM Strong: 3,5 m/sec (137,8 inches) FM Medium: 2,0 m/sec (78,7 inches)
Acceleration	5 g
Mechanical design	Fully enclosed housing with double security systemLaser Protection Class 2 (with laser pointer)X-axis drive with maintenance-free, brushless DC servo motorInPack-Technology for maintenance-free operation
Laser equipment and laser power	 FM Medium and FM Strong: Nd:YVO₄ laser (1064 nm) maintenance-free, air-cooled Lens: 3,2"; Numerous options FM Hybrid: Multiwave Technology, Nd:YVO₄ laser (1064 nm) and air-cooled sealed-off CO₂ laser (10600 nm) Lens: 2,85"; Numerous options

www.trotec.net

Linzer Str. 156 A-4600 Wels Tel. +43 / 72 42 / 239-0 Fax +43 / 72 42 / 239-7380 trotec@trotec.net

www.trotec.net



A COMPANY OF THE trodat GROUP

Laser Systems FineMarker



Nd:YVO₄ Flatbed Lasers for finest markings on metals and plastics

Worldwide Leading Laser Engraving Technology

012X



YAG / YVO₄ technology: More **Power** —More **Possibilities**



Boost your business with the FineMarker from Trotec

Laser marking is already an indispensable technology for many companies in all kinds of industries. It finds new uses every day because of the numerous advantages it provides.

The FineMarker flatbed laser system with Nd:YVO₄ laser source fulfils all the requirements of modern industry. Whether you process individual workpieces or series products, it is the right choice for you.

- Direct marking of metal parts
- Removal of surfaces
- Durable colour change on plastics

Secure your long term investment:

• Efficiency and flexibility

The FineMarker is extremely flexible thanks to its large working area. Large single labels or small series parts—the FineMarker completes orders with maximum efficiency over 720 mm x 430 mm (28 x 17").

• Productivity

Trotec laser technology scores with very high throughput and simple handling. The FineMarker can even label several workpieces in one marking process, while service staff turn to other tasks.

• Great precision and non-contact

The Nd:YVO₄ FineMarker laser source has a very fine laser beam, which makes the precise engraving of 1-point text possible. Our contact-free mechanisms ensure that expensive and delicate parts are not touched during the marking process and thus remain undamaged. The FineMarker is also used for the creation of micro-scripts for protection against plagiarism.

FineMarker Hybrid

Pure Innovation



The first laser system to combine CO₂ and Nd:YVO₄ within a single platform

The Trotec FineMarker Hybrid is the world's first flatbed laser system to combine both CO_2 and Nd:YVO₄ technology. This design increases the range of materials and products that can be processed. Engraving, marking and cutting on one laser system.

Our Multiwave Technology[™] achieves a level of technological integration that was previously thought impossible.

The FineMarker Hybrid is easy to use, technologically advanced and carries all the Trotec family genes.

What Is **Your**Application?


























Applications

- electronic components
- gifts and promotional objects
- parts for the automotive and aviation industry
- components for medical engineering
- type plates
- printed circuit boards
- metal signs
- jewellery
- tin goods
- trophies
- ... and many more

Materials

- bare metals
- coated metals
- untreated metals
- coated plastics
- solid coloured plastics
- acrylics

- cardboard
- ceramics
- paper
- technical textiles
- wood
- ... and many more

A **Complete Package** And a Host of Value Added Accessories



• Laser pointer:

The laser pointer indicates exactly where the laser beam will land on the material, ensuring precise positioning and marking.

• Automatic focus:

Our built-in automatic focus-capabilities work in concert with the auto-focus features of our JobControl software. A high degree userfriendliness is assured.

• Ferromagnetic worktable:

The ferromagnetic worktable of the FineMarker makes positioning of thin materials (e.g. foils) easy.

• Extra dust protection:

Provides added protection for delicate parts such as electronic components and motors for work environments that are prone to dust and dirt.

• Air assist:

Adding air pressure to the processing head as needed improves suction during operation and additionally provides protection for the lens. The air assist is controlled via the Trotec JobControl software.

• Rotary attachment:

Engrave any cylindrical or similar objects such as goblets. Simply load and unload the product with the help of a spring-mounted tension device, which is easy to install and simple to use. Choose from two types of rotary attachments, depending on the size of your workpiece.

• Exhaust systems:

Our exhaust systems take care of the efficient removal of dust and fumes produced during laser operation and ensure the safe and reliable use of your laser for years to come. Another critical factor: you will also be safeguarding the health of your employees and the environment. Trotec offers a wide variety of exhaust systems—from simple ventilators to high-tech filter solutions. Ask your supplier to recommend the ideal extraction system for your application.



Smart **Software** ... for **Tough Jobs**

<u>Eile E</u> dit Engraver <u>P</u> lat	- [Plate1] te Settings V	iew Win	dow Help	0									_
				· 🔳 💣 🐺 🖞 🕴	(% D: 🔿 🤊	160 %		1					-
				David 1						- +			
138.02 mm Y:	6.46 mm	n 🖸 (⊐ □ X:13.0	o mm Y:	-5.97 mm Z:	169.66	mm	3.2 incl	י או 🕹	. .		
ndard 💌	Aluguss		-	ZI 0.00 ₽ S	95.00 V	2.00 10000	P 100.	00 ¥	3.0		1000 皆	2 🖬	
2		4		6 8		10	12		14		Job typ	pe: St	andard
											Resolu		iab 000
T T -						-1		- •				1	1000
trote)C	T	OI	ec't	rote)C [/	ote)C			Orienta	ation: 📀	CAL C
												lour_chang	
111791-117 H-11		-			200	an an ann an		27				lour_chang lour_chang	
trote		te	nt.	ec' t	rote	e ti	ote					lour_chang b med	je5
LIVEG		<u> </u>	VE		IAre		Vic				2_Hu	b_med2	
										-	2 Hu	b_med3 b_med4	
I		I.	- 1	!				-			2_Per 2 Per	n1 n2	
trote	C	TI	Ot	ec't	rote	C 11	ote	C			2_Per 2 Per	n3	
		L			_						2_Sig	n_brass1	
												n_brass2	
	12 12	10 G		2 2 2 2	_	10 CT 10 CT		N			2_Sig	in brass3	
troto		ŧr	nt	ar t	rota	e ti	oto	r			2_Sig 2_Sig	in_brass3 in_brass4	
trote)C	tr	ot	ec t	rote	e tı	ote	C			2_Sig 2_Sig 2_Sig 2_Sig 2_Sig	in_brass3 in_brass4 in_brass5 ainless_stee	el_bracelet
trote	C	tr	ote	ec t	rote	c tı	ote	C			2_Sig 2_Sig 2_Sig 2_Sta 2_Sta 2_Sta 2_Sta	in_brass3 in_brass4 in_brass5 iinless_stee iinless_stee iinless_stee	el_bracelet; el_bracelet;
											2_Sig 2_Sig 2_Sig 2_Sta 2_Sta 2_Sta 2_Sta 2_Sta	in_brass3 in_brass4 in_brass5 iinless_stee iinless_stee iinless_stee	el_bracelet.
trote trote					rote rote		ote ote				2_Sig 2_Sig 2_Sig 2_Sta 2_Sta 2_Sta 2_Sta 2_Sta	in_brass3 in_brass4 in_brass5 iinless_stee iinless_stee iinless_stee	el_bracelet; el_bracelet;
											2_Sig 2_Sig 2_Sig 2_Sta 2_Sta 2_Sta 2_Sta 2_Sta	in_brass3 in_brass4 in_brass5 iinless_stee iinless_stee iinless_stee	el_bracelet; el_bracelet;
trote)C										2_Sig 2_Sig 2_Sta 2_Sta 2_Sta 2_Sta 2_Sta 2_Sta	in_brass3 in_brass4 in_brass5 iinless_stee iinless_stee iinless_stee	el_bracelet; el_bracelet;
	job history	tr	ote	9 <u>c</u> t	rote	c tr	ote)C	×		2_Sig 2_Sig 2_Sta 2_Sta 2_Sta 2_Sta 2_To 2_To 2_To 2_To	in_brass3 in_brass5 iniless_stee iniless_stee iniless_stee iniless_stee ol1 ol2 ol3 ol4 ol5	e_bracelet; e_bracelet; e_bracelet;
trote tr Engraver ID-Numbe	job history	tr	Ot	GC t	Jobnumber	Filename	Oto		×		2_Sig 2_Sig 2_Sig 2_Sta 2_Sta 2_Sta 2_Sta 2_Sta	in_brass3 in_brass4 in_brass5 iinless_stee iinless_stee iinless_stee	e_bracelet; e_bracelet; e_bracelet;
	job history Date 2006-05-19	Start 08-02	ote	9 <u>c</u> t	rote	c tr	ote				2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e_bracelet; e_bracelet; e_bracelet;
trote	job history Date 2006-05-19 2006-05-19	Start 08-02 1	Ot Duration 00-00-06	Jobname 2_Colour_change3	Jobnumber 295	Filename 2_Colour_change3.tef	Kind Standard	dpi 1000			2_Sig 2_Sig 2_Sta 2_Sta 2_Sta 2_Sta 2_To 2_To 2_To 2_To	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e_bracelet; e_bracelet; e_bracelet;
trote tr ^{Engraver} 10-Numbe 2405 2405	job history Date 2006-05-19 2006-05-19 2006-05-19 2006-05-19	Start 08-02 1 08-03 1 08-03 1	Ot(Duration 00-00-06 00-00-06	Jobname 2_Colour_change3 2_Colour_change3	Jobnumber 295 235	Filename 2_Colour_change3.tsf 2_Colour_change3.tsf	Kind Standard Standard	dpi 1000			2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e_bracelet; e_bracelet; e_bracelet;
troto tr 10 Numbe 2405 2405 2407	job history Date 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19	Start 0 08-02 0 08-03 0 08-03 0 08-03 0	Ot(Duration 00-00-06 00-00-06 00-00-06	Jobname 2_Colour_change3 2_Colour_change3 2_Colour_change3	Jobnumber 295 295 295	Filename 2.Colour_change3.tsf 2.Colour_change3.tsf	Kind Standard Standard Standard Standard	dpi 1000 1000			2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e_bracelet; e_bracelet; e_bracelet;
troto tr DNumbe 2405 tr 2407 2408	job history Date 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19	Start 0 08-02 0 08-03 0 08-03 0 08-03 0 08-03 0	Ot (Duration 00-00-06 00-00-06 00-00-06 00-00-06	Jobname 2.Colour_change3 2.Colour_change3 2.Colour_change3 2.Colour_change3	Jobnumber 295 295 295 295 295 295	Filename 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf	Kind Standard Standard Standard Standard Standard	dpi 1000 1000 1000			2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e_bracelet; e_bracelet; e_bracelet;
Engraver In-Number 2405 2406 2407 2408 2409 2400 2401 2402 2403 2404 2405 2406 2407 2408 2409 2401 2411	job history Date 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19 2006-05-19	Start 0 08-02 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0	Duration 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06	Jobname 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3	Jobrumber 295 295 295 295 295 295 295 295 295 295	Filename 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf	Kind Standard Standard Standard Standard Standard Standard	dpi 1000 1000 1000 1000 1000 1000 1000 10		, 1	2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e_bracelet; e_bracelet; e_bracelet;
Eroto Eroto 2405 2406 2406 2407 2408 2409 240	Job history Date 2006-05-19 2006-05	Start 0 08-02 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0	Duration 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06	Jobname Jc_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3	Jobrumber 295 295 295 295 295 295 295 295 295 295	Filename 2.Colour_change3.tsf 2.Colour_change3.tsf 2.Colour_change3.tsf 2.Colour_change3.tsf 2.Colour_change3.tsf 2.Colour_change3.tsf 2.Colour_change3.tsf 2.Colour_change3.tsf	Kind Standard Standard Standard Standard Standard Standard Standard Standard Standard Standard	dpi 1000 1000 1000 1000 1000 1000 1000 10		<u>ک</u>	2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e_bracelet; e_bracelet; e_bracelet;
Erote Errote Errote Errote 2405 2405 2405 2405 2406 2409 240	Job history Date 2006-05-19	Start 0 08-02 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0	Duration 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06	Jobname 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3	Jobrumber 235 235 235 235 235 235 235 235 235 235	Filename 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf	Kind Standard Standard Standard Standard Standard Standard Standard Standard Standard Standard Standard	dpi 1000 1000 1000 1000 1000 1000 1000 10		<u>ع</u> اً	2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e Dracelet e Dracelet e Dracelet
Engraver Indexent	Job history Date 2006/05/19	Start 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-04 0	Duration 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-07 00-00-06	Jobname 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3	Johnumber 295 295 295 295 295 295 295 295 295 295	Filename 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf	Kind Standard Standard Standard Standard Standard Standard Standard Standard Standard Standard Standard Standard	dpi 1000 1000 1000 1000 1000 1000 1000 10			2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e Dracelet e Dracelet e Dracelet
Erote Errote Errote Errote 2405 2405 2405 2405 2406 2409 240	Job history 0 Date 2006-05-19 2006-	Start 0 08-02 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-03 0 08-04 0 08-04 0 08-04 0	Duration 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06 00-00-06	Jobname 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3 2_Colour_change3	Jobrumber 235 235 235 235 235 235 235 235 235 235	Filename 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf 2_Colour_change3.tsf	Kind Standard Standard Standard Standard Standard Standard Standard Standard Standard Standard Standard	dpi 1000 1000 1000 1000 1000 1000 1000 10		, , 1	2. Sig 2. Sig 2. Site 2. Site 3. Site	n_brass3 m_brass4 in_brass5 inless_stee inless_stee inless_stee ol1 ol2 ol3 ol4 ol5	e Dracelet e Dracelet e Dracelet

Make your laser system work for you

Trotec's JobControl software package offers an innovative and intuitive solution for managing engraving and marking tasks with your FineMarker. JobControl is an easy-to-use software programme that provides you with total and flexible control over all laser functions. The software technology features an open design—you can use it with any Windowsbased application, including AutoCAD, CorelDraw, Photoshop, Word, Excel, Acrobat Reader and many more.

Send your layouts directly to the laser via the JobControl printer driver.

Key features include:

- On-the-fly parameter adjustment—even during processing
- Materials database with predefined materials
- Software-AutoFocus for precise focusing with a mouse click
- Multiple positioning: several parts are marked within one marking sequence
- Marker for precise positioning for the most delicate marking tasks
- Job history to track and schedule customer orders
- · Easy replication of all marking and engraving orders
- Remote diagnostics / remote maintenance capabilities

... and many more.

Global Play Local Support



Global presence —now and in the future

Trotec lasers are used all over the world. Our experience in the field with thousands of systems installed is evidence of our **know-how** and **customer trust.**

Our Trotec service and sales partners in more than 80 countries undergo continuous training programmes. Trotec laser systems can therefore be professionally serviced on site.

Trotec Software JobControl also offers the unique possibility of analyzing and evaluating the status of your laser installation. We can provide long distance servicing for rapid diagnosis and high levels of reliability and availability.

For the success of your business—now and in the future.

Our motivation

At Trotec the customer is our top priority. We want you to be even more successful thanks to Trotec. In order to be always able to offer our customers the perfect solution, our aim is innovation. Our innovations provide **minimal overall costs** for your laser system, quality, flexibility, efficiency and **productivity.**

Trotec offers standard and individual solutions. Trotec is the only provider to dispose of a **full range** of innovative flatbed and galvo systems with CO₂, Nd:YVO₄ and fiber laser as well as excimer laser technology.

With intelligent equipment, the know-how of our team and our worldwide service network, we can realize the **ideal solution** for your marking needs at a competitive price.